



# N3006

**Fall 2025 Maintenance  
& Development**

**Weekly Progress Update  
Week of October 6, 2025**





# Weekly Highlight: Tail Inspections

- The tail of N3006 has undergone extensive inspections.
- They checked for any structural wear.
- The flight controls have been removed and inspected.
- Checks involved both bore-scope cameras, and flexible technicians.

**Image:** N3006 without flight controls.



# Flight Controls:

- The tail inspection is the largest inspection to accomplish while N3006 is in Aurora.
- It has gone smoothly, and the team is pleased with the progress.
- Can you spot Paul in the photos?

**Image:** N3006 flight controls under inspection.





# Next Steps:

- Once the tail inspections are complete, the engine inspections will begin.
- The interior is in-work with all elements of the work progressing.
- Major elements such as the lavatory unit, the executive tables, and the drawers have been removed and are in-work.

**Image:** N3006 tail disassembled for checks.

