

N435DK "G-AMPY"

Avionics Upgrade &
Flight Deck Restoration

Weekly Progress
Update

Week of November 11, 2025



Weekly Highlight: Avionics Suite

- All panels have been installed with new avionics and restored gauges.
- All flight deck insulating blankets are made and installed.
- The flight deck restoration is nearing completion with minor squawks being addressed.

Image: N435DK flight deck



Engine Inspections



Image: N435DK #1 Engine De-Cowled

- Engine runs have been accomplished, and the engines have entered inspections.
- Oil leaks are recorded and diagnosed.
- Once inspection corrective actions are complete, the aircraft will be fully airworthy.




Image: N435DK #2 Engine De-Cowled



Finishing Touches...



- The corner of the escape hatch was leaking water during leak tests.
- It was carefully repaired to create a watertight seal.
- Such finishing touches will protect the new flight deck for years to come.

